

Material Safety Data Sheet

Parsitherm 7092CC High Temperature Pure AI. Silicone Code: P6I04-00 Creation Date: 10, Jan. 12 Page 1 of 3

1. Identification of substance: Product name: Parsitherm 7092CC One component high heat resistant aluminum pure Product usage: silicone coating up to 600°C.

Name:	Parsifam Co.
Address:	Km 6, Noor Battery Road, Shahriar City- Iran
Postal Code:	33561-85774
Tel:	+98 21 6576 4960-8
Fax:	+98 21 6576 4969

3. Composition : Contains:

2. Company:

Silicone Resins, Aluminum Pigments, Aromatic Solvents.

4. Hazards Identification :

Avoid naked flames and hot surfaces. NO SMOKING.

Harmful:

Flammable:

5. First Aid Measures : Inhalation:

Do not breathe fume or vapor. Remove patient to fresh air: seek medical attention.

Do not induce vomiting; give patient plenty of water to

Possible risk of irreversible effects in contact with skin.

Eye Contact:

Wash splashes from skin or eyes immediately. Wash eyes with copious amounts of water; if irritation persists seek medical attention.

Skin Contact: Wash splashes from skin or eyes immediately. Remove any contaminated clothing. If symptoms persist seek medical attention.

Ingestion:

drink and seek medical attention. 6. Fire Fighting Measures :

Fire Extinguishing Media: Use foam, dry powder, carbon dioxide. Do not use water jets.

Special Fire Fighting Water can be used to cool containers. Take precautions Procedures: against static discharges.

Protective Wear self-contained breathing apparatus, as combustion will release harmful gases. Wear protective clothing to Equipment: avoid contact with skin.



Material Safety Data Sheet

Parsitherm 7092CC

High Temperature Pure AI. Silicone

Code: P6I04-00 Creation Date: 10,Jan.12 Page 2 of 3

7. Accidental Release Measures :

1.	7. <u>Accidental Release measures :</u>		
	Personal	Avoid contact with skin or eyes; wear protective	
	Precautions:	clothing and ensure adequate ventilation	
	Environmental	Do not contaminate watercourses or ground. Check	
	Precautions :	hollows for vapor build up.	
	Methods for	Cover with sawdust or proprietary absorbent. Sweep up	
	cleaning up:	and then wash area with detergent and water.	
8.	Handling & Storage :		
	Safe Handling	No smoking. Ensure good ventilation. Keep away from all	
	Advice	sources of ignition. Keep away from food, drink and	
		animal feeding stuffs.	
	Storage:	Store in a cool, dry place in sealed containers, away	
		from all sources of heat and ignition.	
9.	9. Exposure Controls / Personal Protection :		
	Respiratory	Ensure good ventilation or wear suitable solvent	
	Protection:	respirator.	
	Eye Protection:	Safety goggles.	
	Hand Protection :	Wear (PVC/Rubber) gloves.	
	Skin Protection :	Wear suitable protective clothing to avoid contact with	

10. Physical & Chemical Properties :

Physical State:	Base: Liquids
Color:	Silver Gray
Odor :	Aromatic Solvent.
Flash Point :	Min. 35°C
Flammability :	Flammable
V.O.C :	≈ 616 g/lit
Oxidizing Properties:	Avoid contact with strong oxidizing agents

skin.



Material Safety Data Sheet

Parsithern 7092CC High Temperature Pure Al. Silicone Code: P6I04-00 Creation Date: 10,Jan.12 Page 3 of 3

Specific Gravity (at 20°C):

1.12 ± 0.05 (g/cc)

Shelf Life (at 20°C) : 12 months

11. Transport Information :

Dispose of according to all state and local applicable regulations.

12. Regularity Information :

R10 :	FLAMMABLE
R40/41 :	HARMFUL; Possible risk if irreversible effects in contact with skin.
513 :	Keep away from food, drink and animal feeding stuffs.
S16 :	Keep away from sources of ignition; NO SMOKING
533 :	Take precautionary measures against static discharges.
536 :	Wear suitable protective clothing.
551 :	Use only in well ventilated areas.

13. Disposal Consideration :

- Kind : Hazardous waste
- Disposal : Do not dispose to drains and domestic trash bins. It can be disposed, when there is no possibility wash out and/or flow to water resources.