# Parsifam Producer of Paints & Coatings

## Material Safety Data Sheet

**Parsi**cyl **3143A** Solvent Based Zinc Phosphate Acrylic Primerr

Code: **P6I04-00** Creation Date: 10,Jan.12 Page 1 of 3

	Primerr			
1. Identification of substance:				
Product name: Product usage:	Parsicryl 3143A As a primer in acrylic or other physically drying anticorrosive paints systems.			
2. <u>Company :</u>				
Name:	Parsifam Co.			
Address:	Km 6, Noor Battery Road, Shahriar City- Iran			
Postal Code:	33561-85774			
Tel:	+98 21 6576 4960-8			
Fax:	+98 21 6576 4969			
3. Composition :				
Contains:	Acrylic Resin, White Spirit, Filler, Pigments.			
4. Hazards Identification	n :			
Flammable:	Avoid naked flames and hot surfaces. NO SMOKING.			
Harmful:	Possible risk of irreversible effects in contact with skin.			
5. First Aid Measures :				
Inhalation:	Do not breathe fume or vapor. Remove patient to fresh air; seek medical attention.			
Eye Contact:	Wash splashes from skin or eyes immediately. Wash eyes with copious amounts of water; if irritation persists seek medical attention.			
Skin Contact:	Wash splashes from skin or eyes immediately. Remove any contaminated clothing. If symptoms persist seek medical attention.			
Ingestion:	Do not induce vomiting; give patient plenty of water to drink and seek medical attention.			
6. Fire Fighting Measure	<u>es :</u>			
Fire Extinguishing Media:	Use foam, dry powder, carbon dioxide. Do not use water jets.			
Special Fire Fighting Procedures:	Water can be used to cool containers. Take precautions against static discharges.			
Protective Equipment:	Wear self-contained breathing apparatus, as combustion will release harmful gases. Wear protective clothing to avoid contact with skin.			



### **Material Safety Data Sheet**

**Parsi**cryl **3143A** Solvent Based Zinc Phosphate Acrylic Code: **P6I04-00** Creation Date: 10,Jan.12 Page 2 of 3

Primer

7.	Accidental	Release	Measures :
•••	neenaontai	1101000	<u>moadar 00 .</u>

	7. Accidental Release measures .		
	Personal	Avoid contact with skin or eyes; wear protective	
	Precautions:	clothing and ensure adequate ventilation	
	Environmental	Do not contaminate watercourses or ground. Check	
		5	
	Precautions :	hollows for vapor build up.	
	Methods for	Cover with sawdust or proprietary absorbent. Sweep up	
	•••••		
	cleaning up:	and then wash area with detergent and water.	
~			
8.	Handling & Storage :		
	Safe Handling	No smoking. Ensure good ventilation. Keep away from all	
	Advice	sources of ignition. Keep away from food, drink and	
		animal feeding stuffs.	
	-		
	Storage:	Store in a cool, dry place in sealed containers, away	
		from all sources of heat and ignition.	
-			
9.	<ol> <li>Exposure Controls / Personal Protection :</li> </ol>		
	Respiratory	Ensure good ventilation or wear suitable solvent	
	Protection:	respirator.	
	Eye Protection:	Safety goggles.	
	Hand Protection :	Wear (PVC/Rubber) gloves.	

Skin Protection : Wear suitable protective clothing to avoid contact with skin.

### 10. Physical & Chemical Properties :

Physical State:	Liquid
Color:	Ocher
Odor :	White Spirit.
Flash Point :	Min. 32°C
Flammability :	Flammable
V.O.C :	≈ 397.50 g/lit
Oxidizing Properties:	Avoid contact with strong oxidizing agents



### **Material Safety Data Sheet**

**Parsi**cryl **3143A** Solvent Based Zinc Phosphate Acrylic Primer Code: P6I04-00 Creation Date: 10,Jan.12 Page 3 of 3

Specific Gravity (at 20°C): 1.50 ± 0.05 (g/cc)

Shelf Life (at 20°C) :

12 months

#### 11. Transport Information :

Dispose of according to all state and local applicable regulations.

#### 12. Regularity Information :

R10 :	FLAMMABLE
R40/41 :	HARMFUL; Possible risk if irreversible effects in contact with skin.
513 :	Keep away from food, drink and animal feeding stuffs.
S16 :	Keep away from sources of ignition; NO SMOKING
533 :	Take precautionary measures against static discharges.
S36 :	Wear suitable protective clothing.
551 :	Use only in well ventilated areas.

#### 13. Disposal Consideration :

- Kind : Hazardous waste
- Disposal : Do not dispose to drains and domestic trash bins. It can be disposed, when there is no possibility wash out and/or flow to water resources.